See note: Who Fills out the EAR? u Initiated by: Region, LP, Central: 707324 Region Enforcement Inv. # Action **REGION 12 - HOUSTON** Enf Case Name of Initiating Office: Referral Rev. 3/18/2002 Media IHW MSW Code:

## Section 1: Respondent

ID	CN600618946				RESP PARTY	
Name .	CES ENVIRONMENTAL SERVICES INC					
Mailing Address	Street/PO Box	4904 GRIGGS RD				
	City/State/Zip	HOUSTON, TX 77021				
	Phone	(713) 676-1460	Fax			

Primary Contac	et (NOE Contact)			
Name	MATT BOWMAN	Organization CES ENVIRONMENTAL SERVICES, INC.		
Title	President And Registered Agent	Phone (713) 676-1460	Fax (713) 676-1676	

## Section 2: Respondent's Facility/Operation (F/O)

F/O ID	RN100693282		35.
F/O Name	CES ENVIRONMENTAL SERVICES	A.	
F/O Physical Address	4904 GRIGGS RD	1	,
Location City	HOUSTON	Location Zip	77021
Location County	HARRIS	Operational Status	Active
Primary Business Activity	Commercial tanker wash/waste pr	Type of Small Entity	Small Business
SNC or HPV?	N/A	SIC Code	4212
Potentially Affected Area	Air, water, land, and human health are potentially impacted.	Complaints Closed	0
List any NOVs?Orders for same or similar violations at this F/O in the past 5 years.	N/A		*
Additional IDs	23198		i i
* · · · · · · · · · · · · · · · · · · ·	30900	2	
	39048 A85775		1.5
	TXD008950461		n tw

Section 3: Summary of Violations

See note: Inclustion of Resolved or Verbal Violations u

Viol Num	Requirements Cited		tion Dates End	Investigation/ File Review	Date of NOV NOE	CAT
65678	Violation Description 30 TAC Chapter 335.6(c)	Start	Unknown	11/05/2008	NOV NOE 08/21/2009	C
						١٢
	CES failed to update Notice of Registra	and the state of t				
365745	30 TAC Chapter 335.2(b)	Unknown	Unknown	11/05/2008	08/21/2009	Α
	PERMIT Provision V.C.1	Unknown	Unknown	11/05/2008	08/21/2009	Α
	CES failed to limit storage of hazardous	s waste to only	those units spe	cified in Permit 39048	3.	
865747	30 TAC Chapter 324.6	Unknown	Unknown	11/05/2008	08/21/2009	С
	40 CFR Chapter 279.22(c)	Unknown	Unknown	11/05/2008	08/21/2009	С
	CES failed to label its used oil containe the site investigation on November 5, 2 pallet at the facility. Investigators also tanks were labeled with the words "use	008, two 55-ga observed that r d oil."	allon drums of us neither the used	sed oil were being sto oil processing nor the	red on a wooden e used oil feed	
72229	30 TAC Chapter 335.6(h)	Unknown	Unknown	11/05/2008	08/21/2009	В
	Failure to submit required recycling noti engaging in recycling activities.	fication forms	for the MEK was	ste stream to TCEQ 9	0 days prior to	
72546	30 TAC Chapter 335.69(a)(2)	Unknown	Unknown	11/05/2008	08/21/2009	С
B. L.	40 CFR Chapter 262.34(a)(2)	Unknown	Unknown	11/05/2008	08/21/2009	C
	Failure to mark hazardous waste contai date.	ners with the v	vords "hazardou	is waste" and an accu	mulation start	
72607	30 TAC Chapter 335.112(a)(8)	Unknown	Unknown	11/05/2008	08/21/2009	- C
	30 TAC Chapter 335.69(a)(1)(A)	Unknown	Unknown	11/05/2008	08/21/2009	c
	40 CFR Chapter 262.34(a)(1)(i)	Unknown	Unknown	11/05/2008	08/21/2009	C
	40 CFR Chapter 265.173(a)	Unknown	Unknown	11/05/2008	08/21/2009	c
	CES failed to keep containers of hazard					
72615	30 TAC Chapter 335.112(a)(8)	Unknown	Unknown	11/05/2008	08/21/2009	С
	30 TAC Chapter 335.69(a)(1)(A)	Unknown	Unknown	11/05/2008	08/21/2009	С
	40 CFR Chapter 262.34(a)(1)(i)	Unknown	Unknown	11/05/2008	08/21/2009	C
	40 CFR Chapter 265.174	Unknown	Unknown	11/05/2008	08/21/2009	С
	CES failed to conduct inspections for the reclaimed at the facility.	e tanker trucks	containing haz	ardous wastes (metha	anol) to be	
72747	30 TAC Chapter 335.2(b)	Unknown	Unknown	11/05/2008	08/21/2009	A
1	PERMIT Provision II A.1	Unknown	Unknown	11/05/2008	08/21/2009	Α
	Failure to obtain a permit modification p 6,500 gallons identified in Table V.C of	100 0	g facility units in	excess of the volume	e equivalent of	
72757	30 TAC Chapter 335.112(a)(9)	Unknown	Unknown	11/05/2008	08/21/2009	Α
	30 TAC Chapter 335.69(a)(1)(B)	Unknown	Unknown	11/05/2008	08/21/2009	Α
	40 CFR Chapter 262.34(a)(1)(ii)	Unknown	Unknown	11/05/2008	08/21/2009	Α
	40 CFR Chapter 265.192(a)	Unknown	Unknown	11/05/2008	08/21/2009	Α
	40 CFR Chapter 265.193(a)(1)	Unknown	Unknown	11/05/2008	08/21/2009	Α
	CES failed to have adequate secondary hazardous waste (EPA waste code D01			hich was determined	to be storing	
72771	30 TAC Chapter 335.112(a)(9)	Unknown	Unknown	11/05/2008	08/21/2009	В.
	30 TAC Chapter 335.69(a)(1)(B)	Unknown	Unknown	11/05/2008	08/21/2009	В
	40 CFR Chapter 262.34(a)(1)(ii)	Unknown	Unknown	11/05/2008	08/21/2009	В
	40 CFR Chapter 265.195(b)	Unknown	Unknown	11/05/2008	08/21/2009	В
	CES failed to conduct daily inspections waste.	for Tank 1002,	which are requi	red for tanks managin	ng hazardous	
74392	30 TAC Chapter 335.4(2)	Unknown	Unknown	11/05/2008	08/21/2009	В
1	30 TAC Chapter 335.4(3)	Unknown	Unknown	11/05/2008	08/21/2009	В
	Failure to maintain facility in a manner to and welfare.	prevent nuisa	ance conditions	and endangerment of	the public health	

. .

## Section 5: Additional Issues

Has the generator completed a hazardous waste determination for each solid waste generated?

Has the generator documented waste classification determinations on all industrial (including non-hazardous) solid wastes? Check the method(s) used for determination:

Item #3

Item #4

CES is to provide the detailed procedures regarding waste determinations of all wash water and explain how the wash water is managed. Of particular interest is how CES manages the first wash batches of wastewater, and how the company determines whether or not these first wash batches can be treated on site. When they cannot be treated on site, where is the wastewater stored until it is shipped off site for disposal?

On November 5, 2008, strong organic odors were observed near waste management unit 103, a nonhazardous sludge box. Waste determination information supplied by CES indicated that this waste stream had last been analyzed in May 27, 2008. TCEQ is concerned that the sludge in the open-topped box is not tested frequently enough to be certain that it is nonhazardous, since the sludge originates from many different drums and tanker trucks.

CES is to provide sampling/testing records from waste stream 90025191, for the calendar years 2008 and 2009.

On December 12, 2008, TCEQ requested information regarding CES's standard operating procedures for determining the RCRA-empty status under 40 CFR 261.7 of incoming tankers and containers destined for cleaning. On January 20, 2009, CES responded with the procedures followed for the tank wash area of the facility. In those procedures, there were no details regarding how the determination is made as to whether a particular vessel is RCRA empty when it arrives, and what documentation is maintained for each vessel when this determination is made.

CES is to develop and submit the procedure used by employees when making the determination regarding the RCRA-empty status of incoming vessels intended for cleaning. If CES intends to claim that vessels are RCRA empty when they arrive for cleaning, documentation must be maintained showing that this determination has been made to minimize the chances that hazardous wastes contained in the vessel are not being treated via dilution from the steam and other cleaning materials used in the tank wash area. Also, CES is requested to provide details of waste management procedures for the heels when it is determined that the incoming vessels are not RCRA empty.

CES is to contact the TCEQ IHW Remediation and Corrective Action Section to determine the current status of WMUs 002 through 009, which are currently listed as closure pending, and update its NOR to reflect the current status of the WMUs.

In addition, it was noted during the March 17, 2009, site visit that the former first flush tank (WMU 101) had been removed from the site without following the TCEQ guidelines for inactivation and closure of a waste management unit. Based on evidence gathered on March 18, 2009, it appears that hazardous wastes may have been stored in this WMU. CES is to proceed with inactivation and closure of the tank pursuant to the guidelines found in 30 TAC 335.8, and to ensure the WMU is noted as closed on its NOR when the process has been completed.

CES claims that the sludge generated in the activated carbon

Item #7

Item #10

Proper management of mixtures of UO & hazardous waste.

40 CFR Part 265 Subpart I, relating to Use and Mangement of Containers?

Item #1

canisters in the solvent recovery process at the facility are exempt from regulation as solid wastes. TCEQ is concerned that the sludges may be exposed to wastes listed in 40 CFR 261, and thus not be eligible for this exemption.

CES is to provide documentation to TCEQ in support of its claim of the sludge exemption. This documentation should include the process by which CES ensures that listed hazardous wastes are not routed through the scrubbers in the solvent reclamation process at the facility.

CES's in-house laboratory provides analytical data that is used to make determinations for compliance purposes (i.e. determines whether wastes can be treated on site, determines if waste oils are spec or off-spec, makes hazardous waste determinations, etc.).

CES is to submit verification that its on-site laboratory has achieved National Environmental Laboratory Accreditation (NELAC) for its laboratory, or other certifications that indicate that the laboratory's analytical determinations can be used to make sound regulatory decisions.

On March 17, 2009, two trucks (Nos. 7253 and 221) containing waste methanol for recycling were observed at CES. Information gathered during the inspection did not reveal the ownership of these trucks, and a manifest (No. 005592569) for truck No. 221 showed that the truck left the generator's facility on March 13, 2009, and arrived at CES on March 16, 2009. CES is listed as the transporter on this manifest.

CES is to submit documentation regarding ownership of the two tanker trucks to the TCEQ Houston Region Office, along with an explanation of where and how this waste stream was managed during the period of time it left the generator's facility and was accepted at CES.

Comparable fuels and syngas fuels are subject to solid waste regulations, unless they meet the exemptions found in 40 CFR §261.38. TCEQ is concerned that the materials that CES sells for fuels do not meet one (or more) of the following exemptions: \*Minimum heating value (5,000 BTU/lbs) \*Viscosity threshold of 50 cs, as fired

CES is to submit documentation to TCEQ proving that the used oils processed and sold as fuel at CES are used oil and are exempt from regulation as solid wastes.

\*Constituent specifications found in Table 1 of 40 CFR §261.38.

On March 17, 2009, four 55-gallon drums containing hazardous (D001) wastes were observed in WMU 105. According to CES personnel, these drums were generated off site by a third party and were transported to CES for bulking, and later disposed of at a hazardous waste treatment facility in Arkansas.

CES is to provide an explanation as to why these drums of hazardous wastes were accepted for transport without proper labels and markings.

On March 17, 2009, two trucks containing a methanol waste stream destined for recycling were observed at CES. On January 20, 2009, the TCEQ Houston Region Office received copies of Notifications for Receiving and Recycling Hazardous or Industrial Waste from CES for the following waste streams:

- \*Water, methanol, and methylene chloride mixture,
- \*Spent pharmaceutical solvent mixture,
- \*Vinyl acetate, water, methanol, methylene acetate, ethylene vinyl acetate, and ethylene vinyl mixuter.

CES is to specify which, if any, of the above notifications applies to the methanol waste stream observed on site on March 17, 2009.

## Section 6: Information About Initiating Office

	Name	BARBARA JOHNSTON	Date 8/21/09
	Signature	Contraca Los	E-Mail BJOHNSTO@tceq.state.tx.us
	Phone	713-767-3756	
	Name	NICOLE BEALLE	Date 8/21/9
£	Signature	Mealh	E-Mail NBEALLE@tceq.state.tx.us
90	Phone	7137673623	8 8